

Technical Bulletin

Place a copy of this bulletin in the front of each Blueprints Manual. Redline drawings as needed and include a TB reference note. Reference TB implementation on site Action Item Box-chart and/or site tool history management log.

 Number:
 055

 Date Issued:
 02/16/06

 Expiration Date:
 02/16/07

Subject/Key Words:	GAMA Genius I/O Interface Board Reset
Classification:	☐ Informational ■ Mandatory ☐ Safety Alert ☐ PM Impact
	Warranty Impact Purchase Parts Por Parts expires / Reference this TB# when ordering NC parts.
Applicable Akrion Procedures:	OP 2031 Change "hold last state" output setting for Genius I/O points
Parts/Reference Documents:	
Attachments:	None

Issue: A hardware/software incompatibility may cause the Genius I/O interface board to

perform a 5-second reset. Normal operation resumes after the reset. During the reset, problems may occur that can lead to damage to tool and/or product damage.

Symptoms: An I/O board reset will register an "Alert" in the data log. It will not impede

operation of the tool unless the robot strikes a tank lid, or a tank goes out of

specifications, preventing product from entering/exiting as scheduled.

Test/Validate: Tools affected: GAMA with Genius I/O systems operated by Series II (Pentium 3)

and Series III (Pentium 4) AKSV6 computers.

Solution: This solution is Mandatory for Series III systems, and recommended for Series II

systems.

Short-Term

Perform OP 2031 on all applicable tool sets to change specific output point configurations. Change the Hold Last State to "yes" for the following: Lid Open Output (process tanks with lids, LuCID, and LuCID2 tanks)

Activate Drain Output (process tanks)

Activate Level Drain Output (process tanks) Open Robot Gripper (active gripper tools).

Long Term

- 1. All Genius Tools factory set with I/O hold last states listed above.
- 2. Computer I/O Cards updated to PCI format

If you have technical questions or require more information, please contact Akrion Technical Support Department via e-mail at techsupport@akrion.com. Authorized service personnel can obtain copies of the latest Akrion procedures and controlled documents from the Akrion Document Control department at doccontrol@akrion.com. Customers must direct all inquires to their local Akrion field service representative. (Form QA1656F1AC)