

Technical Bulletin

Place a copy of this bulletin in the front of each Blueprints Manual. Redline drawings as needed and include a TB reference note. Reference TB implementation on site Action Item Box-chart and/or site tool history management log.

Number: 038 **Date Issued:** 02/01/04 **Expiration Date:** 02/01/05

Subject/Key Words:	Single and Double Column DI Water Heater, Spare Parts, Second Generation Solid State Relays, CC8-c Comparator Boards
Classification:	■ Informational □ Mandatory □ Safety Alert □ PM Impact
	□ Warranty Impact □ Purchase Parts □ No Charge For Parts expires/ Reference this TB# when ordering NC parts.
Applicable Akrion Procedures:	None
Parts/Reference Documents:	Parts: 225939-001, 226040-001 Reference Documents: TB #37: Solid State Relay (SSR) Replacement Kits
Attachments:	None

Replacement spares parts are needed to service Single and Double Column DI Issue:

Water Heater equipped with second generation solid state relays and CC8-c

Comparator Boards

Failures of SSRs or CC8-c comparator boards. **Symptoms**:

The following Akrion part numbers must be used when ordering replacement parts Solution: for these components:

Second Generation SSR: Akrion Part Number 225939-001, KIT SSR **REPL SGL DIW HTR** . Order quantity of 1 for Single Column heaters and quantity 2 for a Double Column heater.

CC8-c Comparator Board: Akrion Part Number 226040-001, DI COMP CKT CC-8c. (This board is compatible with first and second generation SSRs, but not with mercury relays.)

Note: All SSRs must be replaced at the same time. Always use Akrion supplied parts only.