

**Technical Bulletin** 

Place a copy of this bulletin in the front of each Blueprints Manual. Redline drawings as needed and include a TB reference note. Reference TB implementation on site Action Item Box-chart and/or site tool history management log.

 Number:
 07

 Date Issued:
 11

073 11/25/08

Subject/Key Words:	AKS Software; Akrion Systems Name Change Modifications						
Classification:	<ul> <li>Informational</li> </ul>	■ N	/landatory		Safety Alert		PM Impact
	Warranty     Impact	_	'urchase 'arts		No Charge For Parts For Days After Issue Date.		
Parts/Reference Documents:							
Attachments:	None						

**Issue:** Logos and folder/file names in the AKS wet station software have been changed to reflect the Akrion Systems name.

**Solution:** Beginning with version 6.05.029, all references to Akrion will now be displayed as Akrion Systems. This includes all logos, the executable file, the Akrion program folder, and the AKS window title.

Program folder – C:\Akrion is now C:\Akrionsystems Previous version – C:\AK-prev is now C:\AKS-prev

The default supervisor password has not changed.

After installing software version 6.05.029 or greater, a new shortcut must be made to the Akrionsystems executable file which is now under C:\Akrionsystems\bin\Akrionsystems.exe

Note: If you use a batch file to perform backups, you will need to change the command references in the batch file to reflect the aforementioned folder structure.

If you have technical questions or require more information, please contact Akrion Systems Technical Support Department via e-mail at <u>techsupport@Akrion Systems.com</u>. Authorized service personnel can obtain copies of the latest Akrion Systems procedures and controlled documents from the Akrion Systems Document Control department at <u>doccontrol@Akrion Systems.com</u>. Customers must direct all inquires to their local Akrion Systems field service representative. (Form QA1656F1A)